


B4-01-90

Posted on julio 20, 2026 by Carlos Vega







D2-CPB-09 / D2-CPC-19

AREA **ENGINE** •
BAY/COLUMN/ZONE **BLOCKS 1 / R4-Q5 / B4-01-90** •
NETWORK OUTLET **D2-CPB-09 / D2-CPC-19** •

ENERGY EFF **READY** •
UPS **NO** •

FACEPLATE 1 **DAMAGED / BROKE** •

RJ45 JACK A **FUNCTIONAL** •
RJ45 PLUGS **DAMAGED / CLIP BROKEN** •
CONNECTION **FIELD TERMINATED** •

RJ45 JACK B **FUNCTIONAL** •
RJ45 PLUGS **FUNCTIONAL** •
CONNECTION **FIELD TERMINATED** •

ENCLOSURE HARDWARE

CPU **YES / OPERATIONAL** •
MONITOR **YES / OPERATIONAL** •
KEYBOARD **YES / OPERATIONAL** •
MOUSE **YES / OPERATIONAL** •
CONNECTION / **ETHERNET** •
RECOMMENDED PATCHCORD LENGTH **2.5m** •

WORKSTATION HARDWARE

CPU **YES / OPERATIONAL** •
MONITOR **YES / OPERATIONAL** •
KEYBOARD **YES / OPERATIONAL** •

MOUSE **YES** / **OPERATIONAL** •
CONNECTION / **ETHERNET** •
RECOMMENDED PATCHCORD LENGTH **2m** •