




B4-02-100-A

Posted on julio 17, 2026 by Carlos Vega











D5-CPA-15 / D5-CPB-21

AREA **ENGINE** •
BAY/COLUMN/ZONE **BLOCKS 2 / P5-Q5, B4-02-100-A** •
NETWORK OUTLET **D5-CPA-15 / D5-CPB-21** •

ENERGY EFF **READY** •
UPS **NO** •

FACEPLATE 1 **YES** •
FACEPLATE 2 **DAMAGED** •

RJ45 JACK A **FUNCTIONAL** •
RJ45 PLUGS **DAMAGED / CLIP BROKEN** •
CONNECTION **FIELD TERMINATED** •

RJ45 JACK A **FUNCTIONAL** •
RJ45 PLUGS **DAMAGED / CLIP BROKEN** •
CONNECTION **FIELD TERMINATED** •

ENCLOSURE HARDWARE

CPU **YES / OPERATIONAL** •
MONITOR **YES / OPERATIONAL** •
KEYBOARD **YES / OPERATIONAL** •
MOUSE **NO** •
CONNECTION / **ETHERNET** •
RECOMMENDED PATCHCORD LENGTH **1.5m** •

WORKSTATION

CPU **YES / OPERATIONAL** •
MONITOR **YES / OPERATIONAL** •
KEYBOARD **YES / OPERATIONAL** •

MOUSE **YES / OPERATIONAL** •
CONNECTION / **ETHERNET** •
RECOMMENDED PATCHCORD LENGTH **4.5m** •

GMS

CPU **YES / OPERATIONAL** •
MONITOR **YES / OPERATIONAL** •
KEYBOARD **YES / OPERATIONAL** •
MOUSE **YES / OPERATIONAL** •
CONNECTION / **WIFI** •